

AD 2 LHSM STANDARD DEPARTURE CHART INSTRUMENT RWY 16

NAME	PROCEDURE
NALOX1D (32.1)	After departure continue RWY HDG. Climb to FL100. Cross D 4.5 SME DME at 2000 or above then turn left and proceed direct to SME NDB. (Turn limited to 210 KIAS max.) After crossing SME NDB fly on QDR 307 SME NDB proceeding to NALOX. Cross NALOX at FL100.
SUNOR1D (29.5)	After departure continue RWY HDG. Climb to FL100. Cross D 4.5 SME DME at 2000 or above then turn left and proceed direct to SME DME. (Turn limited to 210 KIAS MAX.) After crossing SME NDB turn left to track 135° proceeding to SUNOR. Cross SUNOR at FL100.