Non-AIRAC

# **HUNGARY**

Phone:+361 293 4459 **HungaroControl Pte. Ltd. Co. AIP SUP: 006/2023** 

AFS:LHBPYNYN Hungarian Air Navigation Services Effective Date: 07-DEC-2023

Email:pubsdo@hungarocontrol.hu Aeronautical Information Service End Date: 14-OCT-2024

URL:www.hungarocontrol.hu H-1675 Budapest, POB 80 Publication Date: 24-NOV-2023

Penetrating the Obstacle Limitation Surface of LHBP airport due to activated crane garden next to Terminal 2 areas

#### 1. GENERAL

The objective of this AIP-SUP to inform the relevant personnel about the penetration of obstacle limitations surfaces of LHBP airport by cranes erected between the centrelines of RWY 13L/31R and RWY 13R/31L on the southern side of Terminal 2.

- Declare the penetration of surfaces.
- Determine the position and radius of crane garden with height of crane.
- Declare the obstacle markings and signs, and procedures.

### 2. BACKGROUND

As a part of the airport development plan a construction of a new hotel building has been started next to the existing one, on the southern side of terminal 2 buildings.

During the construction period a crane garden is activated. The number of cranes are between 1 and 4 depends on the status of construction.

### 3. PERIOD OF CRANE GARDEN

The crane garden is active:

From : **06:00 7th of December 2023**To : **18:00 14th of October 2024.** 

Operational period: H24

### 4. POSITION OF CRANE GARDEN AND HEIGHT

The coordinates of the centre position of the crane garden is : 47°25'50.10"N 019°15'47.06"E.

The radius of the crane garden is : **80 m** from the centre position.

Top elevation of the highest crane is : **186 m AMSL.** 

#### **OBSTALCE MARKINGS, LIGHTS AND PROCEDURES** 5.


## Due to height of cranes the inner horizontal surface of the airport obstacle limitations surfaces are penetrated!

All cranes included the booms are marked by red and white strips and lighted by low intensity red obstacle lights according to ICAO ANNEX 14.

In case of the lights are inoperative or other relevant information please contact the airside management of Budapest Airport Pte. Ltd. using the following email address:

Email: airside.bud@bud.hu

#### 6. **CHART**



#### 7. **REPLACED NOTAMS**

This SUP replaces the following NOTAM: A5683/23

AIP SUP 006/2023 2/2 **HungaroControl**